# 9000 ALUMINIUM PAINT

Updated Apr'23

1	NII PA	PPON
90 <b>00 A</b>	UMI	<b>NIUM</b> PAINT
		Latensfied Texture cold 5 Edgew 5 kinwes
	R.	2 <b>.</b> 1000

9000 Alumimium Paint is a ready-mixed aluminium paint which gives a lustrous finish with good durability and protective property.

## Product Features:

- Good durability
- Protective Property

Paint Type	Product Type	Finishing	Recommended Substrate	Pack Size		
Solvent based	Interior & Exterior	Metallic Aluminium Lustre	Metal	1 Litre, 5 Litres		
Composition						
Pigment	: Aluminium					
Binder	: Modified alkyd / Modified phenolic resin					
Thinner	: Hydrocarbon					
Technical Data						
Drying Time	: Touch Dry	: 30 minutes				
	: Hard Dry : 8 hours					
	Drying time above is based on temperature 28 – 32 °C, humidity 70 – 80% and 5% dilution with					
	Nippon Paint General Purpose Thinner.					
Recoating Time	: 8 hours					
-	Recoating time above is based on temperature 28 – 32 °C, humidity 70 – 80% and 5% dilution					
	with <b>Nippor</b>	n Paint General P	urpose Thinner.			
*Important Note:						
Drying Time and recoat	ting time are str	ongly depending	on environment ventilation, paint tl	hickness, environment		
temperature, environm	ent humidity, n	umber of coats a	oplied, thinner used to dilute produc	t and recoat materials. So		
drying time and recoati	ing time provide	ed is for guide onl	у.			
Dry Film Thickness	: Around 25	- 30 um per coat	(based on substrate condition)			
No. of Coats	: 1 - 2 coat					
Theoretical Coverage	: 9 - 11 m <sup>2</sup> per litre per coat (Actual coverage is dependent on substrate condition, applicatio					
	method, application condition and finishing appearance)					
Volume Solid	: ~ 60%					
Shelf Life	: Up to 12 months in tight sealed container					
Application Metho	d					
Brush / Roller	: The paint is ready for use after thorough stirring.					
Conventional Air Spray	-	The paint is ready for use after thorough stirring. If necessary, dilute with 5% of Nippon Paint				
. ,	General Purpose Thinner.					
Recommended Coa	ating System					
Sealer / Primer	: Red Oxide	Primer		: 1 coat		
Top Coat	: 9000 Alum			: 2 coats		
Surface Preparatio	n					
Surface must be dry and	d free from dirt,	grease and other	contaminants. Ferrous substrate sh	ould be sanded or wire-brushe		

Surface must be dry and free from dirt, grease and other contaminants. Ferrous substrate should be sanded or wire-brushed to remove millscales and rust. Clean off dust and dry. The scraped areas should be spot-primed using a primer for metal.



### Cleaning

Clean up equipment with thinner immediately after use.

#### **Safety Precautions**

- Keep container tightly closed and keep out of reach children or away from food and drink.
- Ensure good ventilation during application and drying.
- When applying paint, it is advisable to wear eye protection.
- In case of contact with eye, rinse with plenty of water immediately and seek medical advice.
- Remove splashes from skin by using soap or water.
- Paint must always be stored in a cool place.
- When transporting paint, care must be taken. Always keep container in a secure upright position.
- Dispose any paint waste in accordance with the appropriate Environment Quality Regulations.
- Keep container tightly closed and keep out of reach children or away from food and drink.
- Ensure good ventilation during application and drying.
- When applying paint, it is advisable to wear eye protection.
- In case of contact with eye, rinse with plenty of water immediately and seek medical advice.
- Remove splashes from skin by using soap or water.
- Paint must always be stored in a cool place.
- When transporting paint, care must be taken. Always keep container in a secure upright position.
- Dispose any paint waste in accordance with the appropriate Environment Quality Regulations.

#### Note

\* Theoretical Coverage is based on a mathematical formula

$$\left[\frac{Volume \ Solid \ \% \ x \ 10}{Dry \ Film \ Thickness}\right] = m^2/lit/coat$$

and does not consider LOSS FACTORS.

Variables like porosity of substrate, application method, dilution ratio, dry film thickness, opacity and so on will affect the loss factor and can vary from 30% - 50% or even more.

The above information is given to the best of our knowledge based on laboratory tests and practical experience. However, since we cannot anticipate or control the many conditions under which our products may be used, we can only guarantee the quality of the product itself.

We reserve the right to alter the given without prior notice.